




## MEASURING AND ESTIMATING MATERIALS



Add approx. 5-8% to your actual meterage to cover cutting wastage etc.  
Do not forget accessories such as door bars , underlay , adhesive and scotia.  
Also Care Products like floor protectors and cleaning mops .